

CARDAN LABORATORIES, INC.
PO BOX 541
634 14TH STREET
NORTHERN CAMBRIA, PA 15714-0541
PH: 814-948-8650 FAX: 814-948-5893
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.
DEP CERTIFICATION 11-139

01/18/2019

PATTON BORO
P.O. BOX 175
PATTON, PA 16668

LABORATORY NUMBER: 7068

SOURCE: ID 701

SAMPLED BY: KRT DATE SAMPLED: 01/15/2019 09:30
DATE REC'D..: 01/15/2019 11:55

B A C T E R I O L O G I C A L E X A M I N A T I O N

DATE STARTED: 01/15/2019 13:30 ANALYST: SS
DATE ENDED...: 01/16/2019 13:30 ANALYST: SS

METHOD: SM9223B

* * * * * R E S U L T S * * * * *

	DATE	TIME	ANALYST
TOTAL COLIFORM: ABSENT	01/16/2019	13:30	SS
E-COLI.....: ABSENT	01/16/2019	13:30	SS

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,
except if noted in this report.

CARDAN LABORATORIES, INC.

BY: Scott Semelberger