

CARDAN LABORATORIES, INC.  
PO BOX 541  
634 14TH STREET  
NORTHERN CAMBRIA, PA 15714-0541  
PH: 814-948-8650 FAX: 814-948-5893  
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.  
DEP CERTIFICATION 11-139

06/20/2019

PATTON BORO  
P.O. BOX 175  
  
PATTON, PA 16668

LABORATORY NUMBER: 7327

SOURCE: ID 701

SAMPLED BY: KRT      DATE SAMPLED: 06/18/2019 09:30  
DATE REC'D...: 06/18/2019 11:20

B A C T E R I O L O G I C A L   E X A M I N A T I O N

DATE STARTED: 06/18/2019 14:00      ANALYST: SS  
DATE ENDED...: 06/19/2019 14:00      ANALYST: SS

METHOD: SM9223B

\* \* \* \* \* R E S U L T S \* \* \* \* \*

	DATE	TIME	ANALYST
TOTAL COLIFORM: ABSENT	06/19/2019	14:00	SS
E-COLI.....: ABSENT	06/19/2019	14:00	SS

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,  
except if noted in this report.

CARDAN LABORATORIES, INC.

BY: *Scott Semelberger*